AUSTRALIAN MOBILE RADIO
ABN 85 003 284 222

130 Beaconsfield St Silverwater
N.S.W. 2128

Phone + 61 2 97482622
E-Mail ross@amr.net.au

8th April 2024

RE: Kia Sportage
Registration: [redacted]
VIN: [redacted]

To Whom it may concern,

Details of advice Sought: Inspect vehicles rear demist not functioning.

Nicolas Pratley presented his Kia Sportage 2019, registration [redacted] on Monday the 8th April 2024 at 9.00am. Requiring inspection on the vehicles demist function.

Using the data from the scan tool applied, the following was found.

Signal from the demist switch to BCM (Body Control Module) was at a normal operating function.

In my professional judgement in relation the issue, Further inspection of BCM (Body Control Module) output to the demist relay circuit is required.

Potential issue to be within the body of the harness, or as a result of the body harness installation.

I Josh Morris of [redacted] acknowledge that I have read the experts' code of conduct and am bound by it; I have gained my knowledge and experience as a qualified Automotive Electrician for the past 14 years.

[redacted]

Ross Dietch [redacted]
Managing Director

Joshua Morris [redacted]
Licence: [redacted]